

	COMPANY	LOCATION	COUNTRY:
2014	DALMIA REFRACTORIES	Jamnagar, Gujarat	INDIA
PROJECT DETAIL:	Demolition & Reinstallation of Refractories for 5500 TPD Cement Plant (Shut Down)		
2014	DALMIA REFRACTORIES	Chittorgarh, Rajasthan	INDIA
PROJECT DETAIL:	Refractory lining work for greenfield cement plant (6000 TPD)		
2013 to 2014	DALMIA REFRACTORIES	Jaitaran, Rajasthan	INDIA
PROJECT DETAIL:	Refractory Application works for Greenfield Cement Plant (6000 TPD)		
2013	STEETLEY DOLOMITE	WORKSOP	U.K.
PROJECT DETAIL:	Refractory Lining of Furnace and Pre-heater		
2013	SOLVAY	POVOA DE ST. IRIA	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2013	IDWALA LIME	DANIELSKUIL	SOUTH AFRICA
PROJECT DETAIL:	Construction of 2 Lime Kilns		
2012	EUROPA KRAFT	VIANA DO CASTELO	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2012	CIMPOR	ALHANDRA	PORTUGAL
PROJECT DETAIL:	Refractory repair of Cement Kiln		
2012	PORTUCEL	CACIA	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2012	CELTEJO	V.V. RODAO	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2011	MICROLIME	SEIXAL	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2011	SOPORCEL	FIGUEIRA DA FOZ	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2011	CELTEJO	V.V. RODAO	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		
2011	CMP	MACEIRA	PORTUGAL
PROJECT DETAIL:	Refractory repair of Cement Kiln		
2011	PORTUCEL	VIANA DO CASTELO	PORTUGAL
PROJECT DETAIL:	Repair of a Lime Kiln		

	COMPANY	LOCATION	COUNTRY:
2010	SUIKER UNIE VIERVERLATEN	GRONINGEN	HOLLAND
PROJECT DETAIL:	Repair of a Lime Kiln		
2010	CIMPOR	SOUSELAS	PORTUGAL
PROJECT DETAIL:	Refractory Repair Cement Kiln 1		
2010	CMP	MACEIRA	PORTGAL
PROJECT DETAIL:	Refractory Repair Kiln Hood Line 6		
2010	SMURFIT KAPPA	BIGANOS	FRANCE
PROJECT DETAIL:	Refractory Repair Lime Kiln		
2010	CIMPOR	SOUSELAS	PORTUGAL
PROJECT DETAIL:	Refractory Repair Cement Kiln 3		
2010	SECIL	SETUBAL	PORTUGAL
PROJECT DETAIL:	Refractory Repair Cement Kilns 8 and 9		
2010	CIMPOR	ALHANDRA	PORTUGAL
PROJECT DETAIL:	Refractory Repair Cement Kiln 7		
2010	CIMPOR	SOUSELAS	PORTUGAL
PROJECT DETAIL:	Calciner repair / line 3 Shotcrete		
2010	SECIL	MACEIRA LIZ	PORTUGAL
PROJECT DETAIL:	Kiln Hood reconstruction, line 5 and line 6		
2009	MICROLIME	PAIO PIRES	PORTUGAL
PROJECT DETAIL:	Vertical Lime Kiln repair Shotcrete		
2009	HOLCIM (FRANCE)	ROCHEFORT-SUR-NENON	FRANCE
PROJECT DETAIL:	Refractory repair of a Cement Kiln		
2009	HOLCIM (FRANCE)	ALTKIRCH	FRANCE
PROJECT DETAIL:	Refractory repair of a Cement Kiln		
2009	EKA CHEMICALS AB / AKZO	SUNDSVALL	SWEDEN
PROJECT DETAIL:	Relining of a Vertical Lime Kiln		
2009	VICAT	MONTALIEU	FRANCE
PROJECT DETAIL:	Refractory Repair of a Cement Line		
2009	VOEST ALPINE STAHL GMBH	STEYRLING	AUSTRIA
PROJECT DETAIL:	Refractory Repair of a Lime Kiln (Maerz)		

	COMPANY	LOCATION	COUNTRY:
2008	CELBI	FIGUEIRA DA FOZ	PORTUGAL
PROJECT DETAIL:	Refractory Lining of the new horizontal Lime Kiln		
2008	NORDKAL / SSAB	LULEA	SWEDEN
PROJECT DETAIL:	Refractory Lining of a Lime Kiln (Maerz)		
2008	W&P ZEMENTWERKE	PEGGAU	AUSTRIA
PROJECT DETAIL:	Refractory Repair of a Lime Kiln		
2008	VICAT	BLAUSASC	FRANCE
PROJECT DETAIL:	Refractory repair of a Cement Kiln		
2008	VERDALSKALK	TRONDHEIM	NORWAY
PROJECT DETAIL:	Refractory Lining of a Lime Kiln (Maerz – 300t)		
2008	SECIL	MACEIRA LIZ	PORTUGAL
PROJECT DETAIL:	Line 6, Cyclone 4 Refractory reconstruction	Shotcrete	
2008	VICAT	CRECHY	FRANCE
PROJECT DETAIL:	Refractory Repair of a Cement Kiln		
2008	SECIL	MACEIRA LIZ	PORTUGAL
PROJECT DETAIL:	Line 5, Cyclone 4 Refractory reconstruction	Shotcrete	
2007	CALCIDRATA	ALCANEDE	PORTUGAL
PROJECT DETAIL:	Refractory Lining of a double shaft Lime Kiln project: SIC		
2007	WOPPFINGER Baustoffindustrie	WOPPFINGER	AUSTRIA
PROJECT DETAIL:	Refractory Repair of a Lime Kiln		
2007	SECIL	PATAIAS	PORTUGAL
PROJECT DETAIL:	Major Repair of Kiln Hood, Cooler and Calciner - Shotcrete		
2007	SIVAL	Leiria /Carpalhosa	PORTUGAL
PROJECT DETAIL:	Refractory Lining repair of the "Beau" Furnace		
2006	CIMPOR, SA	SOUSELAS	PORTUGAL
PROJECT DETAIL:	Calciner repair / Line 3 Shotcrete		
2006	E.N.C.I.	MAASTRICHT	NETHERLANDS
PROJECT DETAIL:	Relining of a Cement Kiln		
2006	MICROLIME	PAIO PIRES	PORTUGAL
PROJECT DETAIL:	Vertical Lime Kiln repair shotcrete		

	COMPANY	LOCATION	COUNTRY:
2006	CIMENTS CALCIA	CRUAS	FRANCE
PROJECT DETAIL:	Refractory Repair of a Cement Line		
2006	VA STAHL LINZ KALKWERK	STEYRLING	AUSTRIA
PROJECT DETAIL:	Refractory Repair of a Maerz Lime Kiln		
2005, 2006	SECIL	PATAIAS	PORTUGAL
PROJECT DETAIL:	Shutdown maintenance repairs, line 3		
2005	CIMENTS CALCIA	BEFFES	FRANCE
PROJECT DETAIL:	Refractory Repair of a Cement Line		
2005	C.C.B.	GAURAIN-RAMECROIX	BELGIUM
PROJECT DETAIL:	Major Relining of Cement Line 3 – Kiln and Tower		
2005	CLOGRENNANE LIME LTD	CLOGRENNANE	IRELAND
PROJECT DETAIL:	Refractory Lining of a Maerz Lime Kiln		
2004	HOLCIM (FRANCE) S.A.S.	ROCHEFORT SUR NEUNON	FRANCE
PROJECT DETAIL:	Refractory repair of a Cement Kiln		
2004	CIMENTS CALCIA	BEUCAIRE	FRANCE
PROJECT DETAIL:	Refractory Repair of a Cement Line		
2004	C.C.B.	GAURAIN-RAMECROIX	BELGIUM
PROJECT DETAIL:	Refractory Lining of a Cement Kiln		
2004	CIMENTS CALCIA	RANVILLE	FRANCE
PROJECT DETAIL:	Refractory Repair of a Cement Line		
2003	SECIL	PATAIAS	PORTUGAL
PROJECT DETAIL:	Complete refractory lining of the renewed Line 3		
2002, 2004	SECIL	PATAIAS	PORTUGAL
PROJECT DETAIL:	Line 2, repair works at pre-heater, kiln hood and cooler		
2001	CIMPOR, SA	SOUSELAS	PORTUGAL
PROJECT DETAIL:	Refractory lining and materials procurement of the New Cement Line 3		
2000, 2002, 2003,	SOLVAY	PÓVOA DE ST. IRIA	PORTUGAL
PROJECT DETAIL:	Reconstruction of the refractory lining of the Lime Kilns 3, 5, 1 and 2		
2000	SOLVAY	PÓVOA DE ST. IRIA	PORTUGAL
PROJECT DETAIL:	Refractory Lining of a new Lime Kiln		

COMPANY

LOCATION

COUNTRY:

2000

SIVAL

Leiria /Carpalhosa

PORTUGAL

PROJECT
DETAIL:

Complete Lining of a New Gypsum kiln