

	COMPANY	LOCATION	COUNTRY:
2015	BHUSHAN POWER & STEEL	Lapanga / Rengali	INDIA
PROJECT DETAIL:	Refractory maintenance work for DRI Kilns		
2014	TATA STEEL NEDERLAND BV	Ijmuiden	NETHERLANDS
PROJECT DETAIL:	Pusher Furnace Repair x 3		
2014	ARCELOR MITTAL	Fos sur Mer	FRANCE
PROJECT DETAIL:	Coke Oven Bateries Revamping		
2014	SIDERURGIA NACIONAL	Maia	PORTUGAL
PROJECT DETAIL:	Reheating Furnace Repair x 2		
2014	TATA STEEL NEDERLAND BV	Ijmuiden	NETHERLANDS
PROJECT DETAIL:	Coke Oven - 7 Thru Walls Repair		
2014	TATA STEEL NEDERLAND BV	Ijmuiden	NETHERLANDS
PROJECT DETAIL:	Walking Beam Furnace Repair		
2014	ARCELOR MITTAL SOUTH	Newcastle	SOUTH AFRICA
PROJECT DETAIL:	Blast Furnace + B.Pipe Repair		
2014	ARCELOR MITTAL SOUTH	Newcastle	SOUTH AFRICA
PROJECT DETAIL:	Blast Furnace Repair Project Supervision		
2014	SSAB	Oxelosund	SWEDEN
PROJECT DETAIL:	Annual Refractory Maintenance		
2014	ARCELOR MITTAL	Dunquerque	FRANCE
PROJECT DETAIL:	Walking Beam Furnace Repair		
2014	TATA STEEL NEDERLAND BV	Ijmuiden	NETHERLANDS
PROJECT DETAIL:	Slab Caster Tunnel Kiln Repair		
2014	ARCELOR MITTAL POLAND	Dabrowa Gornicza	POLAND
PROJECT DETAIL:	Refractory Repair of 2 Stoves		
2014	TATA STEEL NEDERLAND BV	Ijmuiden	NETHERLANDS
PROJECT DETAIL:	Refractory Maintenance Contract		
2014	SSAB	Lulea	SWEDEN
PROJECT DETAIL:	Gas Cleaning Plant Repair		
2013	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Reconstruction Program		

	COMPANY	LOCATION	COUNTRY:
2013	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Walking-Beam Furnace Repair		
2013	SIDERURGIA NACIONAL	MAIA	PORTUGAL
PROJECT DETAIL:	Walking-Beam Furnace Repair		
2013	SIDERURGIA NACIONAL	SEIXAL	PORTUGAL
PROJECT DETAIL:	Walking-Beam Furnace Repair		
2013	SSAB	OXELOSUND	SWEDEN
PROJECT DETAIL:	Refractory Maintenance		
2013	INDUSTEEL	LE CREUSOT	FRANCE
PROJECT DETAIL:	Refractory Maintenance of 15 Furnaces (Thermal Treatment and Lamination)		
2013	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Pusher Furnace Repair (x2)		
2013	SSAB	OXELOSUND	SWEDEN
PROJECT DETAIL:	Gas Gun BF Repair		
2013	ARCELOR MITTAL	FOS-SUR-MER	FRANCE
PROJECT DETAIL:	Refractory Revamping of Coke Oven Batteries		
2013	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Refractory Maintenance Contract		
2013	TATA STEEL UK	Port Talbot	UK
PROJECT DETAIL:	Stove Repair		
2013	ARCELOR MITTAL POLAND	Dabrowa Gornicza	POLAND
PROJECT DETAIL:	Blast Furnace Repair		
2012	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Walking-Beam Furnace Repair		
2012	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Reconstruction Program		
2012	SSAB	LULEA	SWEDEN
PROJECT DETAIL:	Stove Burner Chamber Repair		
2012	SIDERURGIA NACIONAL	MAIA	PORTUGAL
PROJECT DETAIL:	Walking-Beam Furnace Repair		

	COMPANY	LOCATION	COUNTRY:
2012	SIDERURGIA NACIONAL	SEIXAL	PORTUGAL
PROJECT DETAIL:	Walking-Beam Furnace Repair		
2012	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Refractory Maintenance Contract		
2012	ARCELORMITTAL	BREMEN	GERMANY
PROJECT DETAIL:	Walking-Beam 1 Complete reconstruction		
2012	ARCELOR MITTAL	FOS-SUR-MER	FRANCE
PROJECT DETAIL:	Refractory Revamping of Coke Oven Batteries		
2011	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Reconstruction Program		
2011	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke-Oven Through Walls Construction		
2011	SAHAVIRIYA STEEL	REDCAR	U.K.
PROJECT DETAIL:	Blast Furnace Repair (start-up)		
2011	ARCELOR MITTAL	SALDANHA	SOUTH-AFRICA
PROJECT DETAIL:	Blast Furnace Taphole Repair		
2011	SIDERURGIA NACIONAL	MAIA	PORTUGAL
PROJECT DETAIL:	Walking-Beam Furnace Repair		
2011	ARCELOR MITTAL	FOS-SUR-MER	FRANCE
PROJECT DETAIL:	Refractory Revamping of Coke Oven Batteries		
2011	SSAB	OXELOSUND	SWEDEN
PROJECT DETAIL:	Blast Furnace BF4 Repair		
2011	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Walking-Beam Furnace Repair (x2)		
2011	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Refractory Maintenance Contract		
2010	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Reconstruction Program		
2010	ARCELOR MITTAL	BREMEN	GERMANY
PROJECT DETAIL:	Full Reconstruction of Walking Beam Furnace		

	COMPANY	LOCATION	COUNTRY:
2010	SIDERURGIA NACIONAL	MAIA	PORTUGAL
PROJECT DETAIL:	Walking Beam Furnace Repair		
2010	ARCELOR MITTAL	SALDANHA	SOUTH-AFRICA
PROJECT DETAIL:	COREX/MIDREX Repair		
2010	ARCELORMITTAL	SCHIFFLANGE	LUXEMBOURG
PROJECT DETAIL:	Post-Combution Furnace Repair		
2010	ARCELOR MITTAL	IMPHY	FRANCE
PROJECT DETAIL:	Refractory Repair of Furnace		
2010	ARCELORMITTAL	DESVRES	FRANCE
PROJECT DETAIL:	STEIN Furnace Repair		
2010	ARCELOR MITTAL	FOS-SUR-MER	FRANCE
PROJECT DETAIL:	Refractory Revamping of Coke Oven Batteries		
2010	ARCELOR MITTAL	GRANDE SYNTHE	FRANCE
PROJECT DETAIL:	Chimney repair		
2010	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Pushing Furnace Repair (x2)		
2010	ARCELOR MITTAL RODANGE	ESCH-SUR-ALZETTE	FRANCE
PROJECT DETAIL:	Refractory Repairs Furnaces and Ducts		
2010	SIDERURGIA NACIONAL	SEIXAL	PORTUGAL
PROJECT DETAIL:	Walking Beam Furnace Repair		
2010	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Refractory Maintenance Contract		
2010	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Minor Blast Furnace Repair		
2010	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Blast Furnace 4 – Iron Troughs		
2009, 2010	ARCELORMITTAL	SCHIFFLANGE	LUXEMBOURG
PROJECT DETAIL:	Combustion Chambers Repair		
2009, 2008, 2007,	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Refractory Repair and Maintenance of Coke Oven Batteries		

	COMPANY	LOCATION	COUNTRY:
2009, 2008, 2007,	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Refractory Maintenance Contract		
2009, 2008, 2007	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Repair		
2009, 2008, 2007	INDUSTEEL	LE CREUSOT	FRANCE
PROJECT DETAIL:	General Refractory Maintenance Contract		
2009	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Reconstruction		
2009	ASCOMETAL	FOS SUR MER	FRANCE
PROJECT DETAIL:	Re-heating Furnace Repair		
2009	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Mixing Chamber of Hot Blast Stove 51		
2009	LUCCHINI SPA	PIOMBINO	ITALY
PROJECT DETAIL:	Repair of a Blast Furnace		
2009	SAARSTAHL AG	VOLKLINGEN	NETHERLANDS
PROJECT DETAIL:	Refractory Repair of 3 Pusher Furnaces		
2008, 2007	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Repair and Reconstruction of Blast Furnace		
2008	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Pig Iron Mixer Relining		
2008	BREMEN STAHLWERKE	BREMEN	GERMANY
PROJECT DETAIL:	Repair of Blast Furnace 3		
2008	ARCELOR MITTAL	SALDANHA	SOUTH AFRICA
PROJECT DETAIL:	Repair of a Blast Furnace		
2007, 2008	ARCELORMITTAL	FOS-SUR-MER	FRANCE
PROJECT DETAIL:	Coke Oven Refractory Repair		
2007	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Major repair of Blast Furnace		
2007	CARSID	MARCINELLE	BELGIUM
PROJECT DETAIL:	Repair of Blast Furnace		

	COMPANY	LOCATION	COUNTRY:
2007	TATA STEEL BV	PORT TALBOT	UNITED KINGDOM
PROJECT DETAIL:	Coke Oven Repair		
2007	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Repair of Blast Furnace		
2007	TATA STEEL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Re-heating Furnace Repair		
2007	SIDMAR	SERAING	BELGIUM
PROJECT DETAIL:	Repair of Blast Furnace 3 and 6		
2007	ARCELOR MITTAL	VANDERBIJLPARK	SOUTH AFRICA
PROJECT DETAIL:	Blast Furnace Repair / Wind Pipe System Relining		
2006	CORUS STAAL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	BF 7 shutdown – Full reconstruction of the Pelletizing Furnace, Blast Furnace Bunkers and 2 Pusher Furnaces		
2006	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Re-heating Furnace Repair		
2006	CORUS	PORT TALBOT	UNITED KINGDOM
PROJECT DETAIL:	Hot Repair of a Hot Blast Stove		
2006	CORUS STAAL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Full Repair of Blast Furnace 7 /		
2006	SOLAC	FOS SUR MER	FRANCE
PROJECT DETAIL:	New Coke Oven Construction		
2006	SOLAC	DUNKERQUE	FRANCE
PROJECT DETAIL:	Blast furnace Repair		
2005, 2008	SIDERURGICA SEVILLANA, S.A.	ALCALÁ DE GUADAIRA	SPAIN
PROJECT DETAIL:	Re-heating Furnace Repair		
2005, 2004	PREUSSAG STAHL	SALZGITTER	GERMANY
PROJECT DETAIL:	Major Repair of Blast Furnace		
2005	EKO STAHL	EISENHÜTTENSTADT	GERMANY
PROJECT DETAIL:	Major Repair of 2 Blast Furnaces		
2005	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Repair of Blast Furnaces		

COMPANY

LOCATION

COUNTRY:

Year	Company	Location	Country
2005	BREMEN STAHLWERKE	BREMEN	GERMANY
PROJECT DETAIL: Repair of Blast Furnace			
2004	EKO STAHL	EISENHÜTTENSTADT	GERMANY
PROJECT DETAIL: Major Repair of Blast Furnace			
2004	ILVA	TARANTO	ITALY
PROJECT DETAIL: Full Repair of Blast Furnace			
2004	COCKERILL SAMBRE OUGREE	OUGREE	BELGIUM
PROJECT DETAIL: Repair of Blast Furnace			
2004	VOEST ALPINE STAHL	LINZ	AUSTRIA
PROJECT DETAIL: Bustle Pipe System Lining			
2003, 2004, 2005,	CORUS STALL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL: General Refractory Maintenance Contract			
2003, 2004, 2005,	CORUS STALL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL: General Refractory Maintenance Contract			
2003	SIDMAR	GENT	BELGIUM
PROJECT DETAIL: Blast Furnace Repair			
2002	CORUS	PORT TALBOT	UNITED KINGDOM
PROJECT DETAIL: Stove Repair			
2002	CORUS STAAL BV	IJMUIDEN	NETHERLANDS
PROJECT DETAIL: Major Repair of Blast furnace			
2002	SETFORGE	LA CLAYETTE	FRANCE
PROJECT DETAIL: Furnaces Repair			
2001, 2002	SSAB	LULEA	SWEDEN
PROJECT DETAIL: Coke Oven Hot Repair			
2001, 2002	THYSSEN KRUPP STAHL AG	SCHWELGERN	GERMANY
PROJECT DETAIL: New Coke Oven Battery Construction			
2001	SSAB	OXELOSUND	SWEDEN
PROJECT DETAIL: Coke Oven Hot Repair			
2001	SIDMAR	GENT	BELGIUM
PROJECT DETAIL: Repair of 3 Stoves			

	COMPANY	LOCATION	COUNTRY:
2001	SOLAC	DUNKERQUE	FRANCE
PROJECT DETAIL:	Mixer, Compensators and Wind Pipe Relining		
2001	LUCCHINI SPA	PIOMBINO	ITALY
PROJECT DETAIL:	Construction of a New Coke Oven Battery		
2000, 1999, 1998,	PREUSSAG STAHL	SALZGITTER	GERMANY
PROJECT DETAIL:	Coke Oven Maintenance		
2000	HKM	DUISBURG	GERMANY
PROJECT DETAIL:	Pig Iron Mixer Relining		
2000	SOLAC	FOS SUR MER	FRANCE
PROJECT DETAIL:	Stove Repair		
2000	SSAB	LULEA	SWEDEN
PROJECT DETAIL:	Blast furnace Repair / Stove Relining		
2000	LUCCHINI SPA	TRIESTE	ITALY
PROJECT DETAIL:	Complete Stove Relining		
1999, 2000	HOOGOVENS	IJMUIDEN	NETHERLANDS
PROJECT DETAIL:	Coke Oven Maintenance/Repair		
1999, 2000	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Full Repair of Blast Furnace 5		
1999	BREMEN STAHLWERKE	BREMEN	GERMANY
PROJECT DETAIL:	Blast Furnace Hot Blast Main Complete Relining		
1999	ILVA	TARANTO	ITALY
PROJECT DETAIL:	Coke Oven Construction		
1999	LUCCHINI SPA	TRIESTE	ITALY
PROJECT DETAIL:	Coke Oven Repair		
1998	EKO STAHL	EISENHÜTTENSTADT	GERMANY
PROJECT DETAIL:	Reconstruction of a Maerz Furnace		
1998	ZENTRAL COKEREI SAAR	DILLINGEN	GERMANY
PROJECT DETAIL:	Coke Oven Repair		
1998	SSAB	LULEA	SWEDEN
PROJECT DETAIL:	Blast Furnace Repair / New Stove Construction		

	COMPANY	LOCATION	COUNTRY:
1998	LUCCHINI SPA	PIOMBINO	ITALY
PROJECT DETAIL:	Repair of a Blast furnace / Complete Refractory Wind Pipe System Relining		
1997, 1996, 1995	PREUSSAG STAHL	SALZGITTER	GERMANY
PROJECT DETAIL:	Maintenance and Repair of Walking Beam Furnace and Ladles		
1997 to 2010	SIDERURGIA NACIONAL	MAIA	PORTUGAL
PROJECT DETAIL:	Construction of Re-heating and Walking Beam Furnaces / General Maintenance Works		
1997	EKO STAHL	EISENHÜTTENSTADT	GERMANY
PROJECT DETAIL:	Repair of Blast Furnace		
1996 to 2008	SSAB	OXELOSUND	SWEDEN
PROJECT DETAIL:	General Maintenance Works / Blast Furnace and Walking Beam Repairs		
1996	EKO STAHL	EISENHÜTTENSTADT	GERMANY
PROJECT DETAIL:	Repair of Walking Beam Furnace		
1996	SOLAC	DUNKERQUE	FRANCE
PROJECT DETAIL:	New Coke Oven Construction (B7)		
1996	PREUSSAG STAHL	BRANDENBURG	GERMANY
PROJECT DETAIL:	Walking Beam Furnace Repair		
1995 to 1997	THYSSEN KRUPP STAHL AG	DUISBURG	GERMANY
PROJECT DETAIL:	Walking Beam Furnace Repair / Mixer Relining		
1995	EKO STAHL	EISENHÜTTENSTADT	GERMANY
PROJECT DETAIL:	Lining of a New Blast Furnace and Stove		
1994 to 2001	SIDERURGIA NACIONAL	SEIXAL	PORTUGAL
PROJECT DETAIL:	Maintenance Works at Coke Oven Battery Repair of Pig Iron Mixer / Repair of Galvanization Furnace / Maintenance of Steel Ladles and Tundishes / Acid Resistant Lining of Tanks / General Maintenance Works		